

Notification of Hazardous Waste Site

United States Environmental Protection Agency Washington DC 20460

This initia	al notificat	ion info	rmation is	;
	y Section			
hensive E	nvironmer	ital Resp	onse, Coi	npen
	d Liability			
be mailed	hy June 9	1981		

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

PAS 000 001 300

	be mailed by June 9, 1981.	ia mast	winer applies.	· •		K
			8106	09		
4	Person Required to Notify:		· · · · · · · · · · · · · · · · · · ·			
	Enter the name and address of the pe		Name BP OIL I	NC.		
or organization required t	or organization required to notify.		Street P.O. BOX	428		
			city MARCUS H	ООК	State PA	Zip Code 19061
	<u> </u>					15001
3	Site Location: Enter the common name (if known) and actual location of the site.		Name of Site RP OT	L INC, MARCUS H	OOK DEETN	EDV
			Name of Site 21 01	2 Ind, Patroco II	OOK KLIIN	TIVI
ac			Street POST	ROAD		
PAD 406-800 LUGAS			city MARCUS HO	OK County DELAWAR	E State PA	Zip Code 19061
<u></u>	Person to Contact:					
	Enter the name, title (if applicable),	. and	Name (Last, First and Title)	MARTINI, S.C.,	ENGINEER	ING SPECIALIST
4	iness telephone number of the person		Phone (215) 49	4-3600, EXTENSI	ON 351	
14	contact regarding information submitted on this form.					4
P	AD 07 162 2683					,
)	Dates of Waste Handling:		_	· · · · · · · · · · · · · · · · · · ·		
	Enter the years that you estimate v treatment, storage, or disposal beginned at the site.		From (Year) 1949	To (Year) PRESEN	r 1981	·
•	Waste Type: Choose the option Option I: Select general waste type you do not know the general waste encouraged to describe the site in I	es and so types or	urce categories. If sources, you are		and Recovery	persons familiar with the Act (RCRA) Section 3001
	General Type of Waste: Splace an X in the appropriate	Source o	-	Specific Type of Wast EPA has assigned a folisted in the regulation appropriate four-digit rethe list of hazardous w	e: ur-digit number s under Section number in the b astes and code	r to each hazardous wasten 3001 of RCRA. Enter the boxes provided. A copy of its can be obtained by e State in which the site
	1. ☐ Organics	1. 🗆 Mir	ning	located.		•
	•		nstruction	K051		
	3. Solvents	3. □ Tex		K052		
		4. □ Fer				
			per/Printing other Tanning			
			n/Steel Foundry			
			emical, General	-		
			ting/Polishing			
	·		itary/Ammunition			<u> </u>
	·		ctrical Conductors			PC
			nsformers	L		


13. ☐ Utility Companies
14. ☐ Sanitary/Refuse
15. ☐ Photofinish
16. ☐ Lab/Hospital
17. ☐ Unknown
18. ☐ Other (Specify)


SEMS DocID


2343166

	Notification of Hazardous Waste Site	Side Two	* . ·	_
F	Waste Quantity: Place and X in the appropriate boxes to indicate the facility types found at the site. In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons. In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.	Facility Type 1.	Total Facility Waste Amount cubic feet gallons BEST ESTLIATE - 66,00 Total Facility Area square feet REST ESTLIATE - 8,1 acres	
G	Known, Suspected or Likely Releases to Place an X in the appropriate boxes to indicate or likely releases of wastes to the environment	te any known, suspected, nt.	☐ Known ☐ Suspected ☐ Likely ☒ Nor	
	Note: Items Hand I are optional. Completing hazardous waste sites. Although completing	these items will assist EPA and State and the state items is not required, you are enco	and local governments in locating and assessi ouraged to do so.	ing
H	Sketch Map of Site Location: (Optional Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.	See attached map		
				T.
ī	conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which h may help describe the site conditions.	impoundment 60,000 Ft. ² 11 waste (5,000,000 gal ludge) was chem-fixed a n Deptford, NJ. An ad azardous waste are loca	lons of API Separator nd sent to Kinsley Landfilditional 66,000 gallons of	
	•			
J	Signature and Title: The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other"	Name E.S. KULINSKIZ.S. (Street City State Signature	Owner, Present Owner, Present Owner, Past Transporter Operator, Prese Operator, Past Other	

ENVIRONMENTAL PROTECTION AGENCY NOTIS DATA MANAGEMENT SYSTEM COMMENT MAINTENANCE FORM








BP Oil Inc.

MARCUS HOOK, PA. 19061





United States Environmental Protection Agency Region III Sites Notification Philadelphia, Pennsylvania 19106

RETURN RECEIPT REQUESTED